


Date:

14/02/2018



## Commentary

An aditional machine was run for regulating reserve as other units would have been used but actions were not necessarily required.

Trades were carried out on the interconnectors for ROCOF and margin. Some BM actions were taken due to too much wind in Scotland to reduce power across the border. Some BM actions were carried out for voltage support overnight in South Wales.