

Code Administrator Meeting Summary

Meeting Name

CMP317 Identification and exclusion of Assets Required for Connection when setting Generator Transmission Network Use of System (TNUoS) charges

Date: 3 September 2019

Contact Details

Chair: Rob Marshall

Contact details: Rob.Marshall@nationalgrideso.com
07824 518958

Proposer: Harriet Harmon, National Grid ESO
Harriet.Harmon@nationalgrideso.com

Key areas of discussion

The Workgroup discussed the following:

The workgroup considered suggestions from a workgroup member in regards to defining each of the elements of the regulation 838/2010, an issue which had been raised at previous workgroups.

- The discussions focused on how the elements of this regulation could be clearly defined for the purpose of this modification. For each element, various scenarios and permutations were discussed, in order to ensure any definitions were fit for purpose and robust to deal with varying scenarios.
- The workgroup continued to explore where in the €0-€2.50/MWh range should be targeted.
 - There were discussions that touched upon whether a “broad brush” approach, targeting the middle of the €0-2.50MWh range would be preferable, or whether targeting either end of the scale would be more beneficial.

- Discussions were also held around the “pre-exisitng” network tests required, and whether there was a difference between these tests and the “but for” tests suggested previously by Ofgem.

The Workgroup agreed that the following next steps:

- The workgroup would indicate their availability for the next workgroup, to be held in late September/Early October.

Actions Log

Number	Action	Status
5	ESO to send out latest MITS Map	Open
6	HH to firm up rules, definitions and “What ifs”	Closed
8	Ofgem to provide a summary of any views they hold that are relevant to this modification	Open
9	ESO to update diagrams shared with workgroup showing physical assets required for connection	Open
10	GG and JT to look at definition for assets require for connection	Open

For further information, please contact the Code Administrator.