

Code Administrator Meeting Summary

Meeting Name: GC0107/113 Workgroup 7

Date: 10 July 2019

Contact Details

Chair: Paul Mullen

Contact details: paul.j.mullen@nationalgrideso.com

Proposer: Rob Wilson

Contact details: robert.wilson2@nationalgrideso.com

Key areas of discussion

- Workgroup meeting discussed the legal text and the content of the workgroup report.
 - Discussions over most appropriate format of template – a workgroup consultation question will be asked on this subject.
 - Noted that the template to capture the values/requirements only covers the solution for GC107. However, the principles applied in producing the GC0107 consolidated template will be applied when producing the GC0113 consolidated template.
 - On implementation, workgroup agreed to a 3-month transition period from date of implementation for Network Operators to establish their processes to meet the new obligations and Network Operators (including ESO) would have 10 Business Days from when new or revised bilateral agreement has been entered into to notify the ESO of the updated values/requirements. ESO would then have a further 5 Business Days from such notification to publish the updated values/requirements.
- A workgroup member presented 2 possible alternatives. In summary, these are:
 - Limiting the application of the modification to those parties with a CUSC contract or other ESO bilateral contract; and
 - DNOs still populating the data for the original template but would not then subsequently update this information should there be any individual sites where a non-standard value was agreed for that site.

Next steps

The Workgroup agreed that the following next steps:

- Updated legal text and workgroup report to be issued to workgroup 11 July 2019;
- Workgroup to provide showstopper comments on legal text and workgroup report by 18 July 2019;
- Next meeting arranged (if needed) for 23 July 2019 to discuss showstopper comments; and
- Workgroup consultation to be issued 26 July 2019.

Actions from this workgroup meeting (all added to action log)

For further information, please contact the Code Administrator.